



# AIR QUALITY MONITORING MONTHLY MONITORING REPORT CARNWATH ROAD RIVERSIDE (CARRR) JANUARY 2019



**Figure 1 Graph of 15-min PM<sub>10</sub> Concentrations at CARRR/AA/1: January 2019**



**Figure 2 Graph of 15-min PM<sub>10</sub> Concentrations at CARRR/AA/2: January 2019**




Figure 3 Graph of 15-min PM<sub>10</sub> Concentrations at CARRR/AA/3: January 2019





Figure 4 Graph of 15-min PM<sub>10</sub> Concentrations at CARRR/AA/4: January 2019





Osiris Monitor ID	Average PM <sub>10</sub> Concentration (µg/m <sup>3</sup> )	Data Capture (%)	Number of Exceedances of the 15-Minute PM <sub>10</sub> Alert Level of 250 µg/m <sup>3</sup> .
CARRR/AA/1	11.5	100	0
CARRR/AA/2	16.0	53.1	1
CARRR/AA/3	11.9	100	0
CARRR/AA/4	8.3	100	0

### PM<sub>10</sub> Alert Level Exceedance Investigation Summary

Alert ID	Source of Dust
CARRR/AA/2_W 3_1	Monitor being worked and maintained to be put back online